



Note:  
the sketch above shows a renovation  
to an existing building

it is strongly recommended that the existing  
building has a termite inspection before  
any new works.

 **KORDON TERMITE BARRIER**



Bayer Environmental Science

Subject

Sheet No.

retaining wall - detail 1

**kd 021**