

KORDON TB

installed on perimeter hob under steel bottom channel to extend down slab edge passed trim as shown

setdown to wet area floor

topping slab

structural slab

KORDON TMB

to wrap Kordon back over tophat holding channels as shown. installation would be carried out in conjunction with the blue board assembly

Note: this inspection zone is vital for the prevention of termite entry

as result this zone should be kept to a maximum

blockwork face

maximum