


sketch below shows a existing slab floor to a factory  
the expansion material has deteriorated over time and in need of  
replacing.  
It was suggested that in replacing the expansion material Kordon TB  
could be installed to assist the pervention of concealed termite entry



**Kordon**<sup>®</sup>



**kd045**

Subject:

**Renovation detail 1**